FITNESS CERTIFICATE

1.	Name of the School	: Bhavan's Vivekananda Vidhya mandir Senior Secondary School, manvila, Tum Snot: Creeklu Prasanth
2.	Name of the Officer	
3.	Period for which the Certificate is issued	: 2024 - 25
4.	Classification of the building and size (basis for classification) (See Annexure 1) (i) Permanent Single or multistoreyed (ii) Semi-permanent (iii) Temporary shed	: Bbishma Block - 804 m², 18.04m vya8a block - 9580.67 m², 12.25m. : Crandhi block - 342.66m², 6.95m.
5,	Nature of defects if any (a) Foundation and basement (b) Superstructure (c) Doors and Windows (d) Wood work wrought and put up (e) Roof (f) Flooring (g) Miscellaneous (Craks etc.)	R.C.C. Colourn of footings R.C.C. Pramed Aructure. Teak wood. R.C.C. 100f Comunt plastered
δ.	Any major defects noticed which will render the building unsafe in any manner	: Nil
7.	Whether maintenance works have been done properly	: Mad Yes
8.	Whether the structure is sound or not for conducting classes	: Yes. Structure is sound under normal weather and wind condition.
Noi	wind, exposure to flood etc.	be examined also with reference to location, altitude, intensity of med necessary for the certificate may be furnished separately
	with the certificate.	med necessary for the evillent may be random soprately
	Certified that the school was inspected b	y me on
and	found to be fit to conduct classes for the	period 2024 - 25 circles mana/
		cenchinens for the reasons stated above.
		a Alen
Plac	et:	Signature: Assistant Engineer
Dat	e:	Designation: Lacol Sulf Generament Department Theresenanthoperform